



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Report Date: September 29, 2006

Supervisor 1027

Mine Name: Goldstrike Project
Operator Name: USMX of Utah

Permit number: M/053/005
Date: September 13, 2006
Time: 5:00 PM

Inspector(s): Doug Jensen
Other Participants: None
Mine Status: Reclaimed

Weather: Clear, warm

| Elements of Inspection | Evaluated | Comment | Enforcement |
|--|--------------------------|--------------------------|--------------------------|
| 1. Permits, Revisions, Transfer, Bonds | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Public Safety (shafts, adits, trash, signs, highwalls) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Protection of Drainages / Erosion Control | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4. Deleterious Material | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. Roads (maintenance, surfacing, dust control, safety) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. Concurrent Reclamation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 8. Water Impoundments | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 9. Soils | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. Revegetation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 11. Air Quality | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 12. Other | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Purpose of Inspection:

Inspected the site to check whether the fire that went through the area this spring impacted the site.

Directions to Site:

See previous inspection reports.

Inspection Summary:

The fire had impacted some of the areas within the site, but those areas have begun to recover. The site has received several good storms since the fire therefore the vegetation has had sufficient moisture to recover.

Took several pictures showing the vegetation in the burned over areas. The pictures are included in this report.

Conclusions and Recommendations:

This site has not been released by the BLM or Division of Water Quality therefore I will continue to monitor the site when I am in the area.

Inspector's Signature

Doug Jensen

Date:

9/28/06

dj:pb

cc: Russ Schreiner, BLM, St George FO

O:\M053-Washington\M0530005-Goldstrike\inspections\09142006insp.doc







09.13.2006

09.13.2006 14

09.13.2006 14:35